Water Fund Capital Outlay Requests Adopted Budget FY2019-20

	Regulatory						Cost		
Fund	Cost Center	Account	Account	Description	New/Replacement	Qty	Per Unit	Total Justification	
497	PS51A	15041_0000	10500	Additional cost for replacement of #236	R-Replace	1	75,000	75,000 Additional funding for equipment 236 water crew tool equipment.Replacement costs exoriginal budgeted amount.	xceeded
497	PS51A	15041_0000	10500	Backhoe	R-Replace	1	175,000	175,000 Backhoe equipment replacement due to high usage and frequent maintenance.	
497	PS51B	15041_0000	10500	Misc	R-Replace	1	10,000	10,000 Replace misc. water construction equipment . (pumps, pavement saws, tapping mach etc)	ines
497	PS51D	15041_0000	10500	Mid size sedan	R-Replace	1	4,600	4,600 Replace vehicle due to high use and high maintenance	
497	PS51D	15041_0000	10500	Compact sedan	R-Replace	1	4,600	4,600 Vehicle in worn condition requiring high maintenance	
497	PS51D	15041_0000	10500	Diesel Particulate Filter on Dump Truck #150	R-Replace	1	2,875	2,875 Replace Diesel Particulate Filter per CARB California Air Resources Board regulatory	mandates
497	PS51D	15041_0000	10500	Corporate hardware replacement	R-Replace	1	5,750	5,750 Replace end of life and end of support corporate technology servers and network equi	ipment
497	PS51D	15041_0000	10500	Storage Server for Data backups	R-Replace	1	3,220	3,220 Replacement needed due to server end of life and out of warrantry	
				ATER FUND TOTAL CAPITAL OUTLAY REQUESTS				281,045	